









 2 sec.  save constant




 1x  recall constant


 2x  history (1-20)



 +  2 sec. delete history









 1x 



  2 sec. 





 2x 

  2 sec. 





 1x  horizontal measurement permanent on


 2x  horizontal measurement off



 1x 




  2 sec. 











 MENU



 2 sec.  1.1 unit



  2.1 unit 



  3.1 trl


  4.1 BEEP


  5.1 LEVEL

  6.1 ILLU

  7.1 rESEt


 or  changes settings in submenu

 2 sec. saves all changed settings

 exit menu without changes

QUICKSTART

Leica DISTO™ D3a BT



- | | |
|--------------------------|-----------------------------------|
| 1 ON/DIST (on/measuring) | 8 Functions |
| 2 Smart Horizontal Mode | 9 Timer |
| 3 Plus (+) | 10 2 nd for navigation |
| 4 Minus (-) | 11 Menu/equal |
| 5 Area/volume | 12 Clear/OFF |
| 6 Storage/Memory | 13 Bluetooth® |
| 7 Reference | |

- when it has to be right



ON DIST

1x → ON

CLEAR OFF **2 sec. → OFF**

ON DIST **1x**

Bluetooth **2nd**

Bluetooth® on

- 1x send**
- 2 sec. send all**
- 2nd**

1x

max. +45°

max. -45°

2x

2 sec.

A = A1 + A2 + A3

3x

a ≠ b

a = b

4x

5x

6x



Laser class 2 in acc. to IEC 60825-1

www.disto.com



SAP. No. 776 756a

